

Interim Reclamation Inspection

November 25, 2020

Operator: K P KAUFFMAN COMPANY INC - 46290

API: 05-123-10240

Inspection Document #: 697502213

Weld County, CO

SESW Section 21 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LEONARD #24-21
API: 05-123-10240



Photo 1. Photo taken illustrates the Operator well sign.

Inspection Photos
Location Name: LEONARD #24-21
API: 05-123-10240



Photo 2. Photo taken from the well location, facing North. Photo illustrates an unused pumping unit.

Inspection Photos
Location Name: LEONARD #24-21
API: 05-123-10240



Photo 3. Photo taken from the well location, facing Northwest. See comments under Photo 2.