

# *Inspection Photos*

*API# 081-06741*

*Operator: Argali*

*Insp#: 692402726*

*Insp Date: 11/20/2020*



Photo#1:

Overview of Location to Northwest. Insert is meter shed (?) at North end of Pad.

November 20, 2020



Photo#2:

Overview of Location to Southeast. Unknown riser and unmarked Anchor at Shed.

November 20, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Argali PA Federal API#081-06741