

Inspection Photos

Location Name: LARAMIE ENERGY LLC Laramie Land & Cattle Co /36-10 Pad

Location ID: 334516



Photo #2336 from entrance to location.



Photo #2337 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Laramie Land & Cattle Co /36-10 Pad

Location ID: 334516



Photo #2338 Sediment is being transported off of location due to tracking.



Photo #2339 Sediment is being transported off of location due to tracking.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Laramie Land & Cattle Co /36-10 Pad

Location ID: 334516



Photo #2340 Sediment is being transported off of location due to tracking.




Photo #2341 Access road.