

Inspection Photos
Location Name: Simms #1A
API: 05-067-06344



Simms #1A location photo.



Simms #1A well head. Dual completion.

Inspection Photos
Location Name: Simms #1A
API: 05-067-06344



Unused equipment near well head.



Simms #1A production equipment.

Inspection Photos
Location Name: Simms #1A
API: 05-067-06344



Conduit with wires protruding from the ground.



Exposed wires near entrance to location.