

Inspection Photos

API: 071-06559

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/30/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06559 | Date: 11/30/2020

Inspection Photos



Photo 1. Facing northwest toward the location. The location has been seeded and stabilized with hydromulch.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06559 | Date: 11/30/2020

Inspection Photos



Photo 2. The fill slope has been seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06559 | Date: 11/30/2020