

Inspection Photos

API: 071-09173

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/30/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09173 | Date: 11/30/2020

Inspection Photos



Photo 1. Facing southeast along the access road. Stormwater is directed across the road causing erosion of the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09173 | Date: 11/30/2020

Inspection Photos



Photo 2. Facing toward the fill slope of the road showing the erosion at Lat/Long:37.14779,-104.78849.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09173 | Date: 11/30/2020

Inspection Photos



Photo 3. Culvert along the access road is partially filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09173 | Date: 11/30/2020

Inspection Photos



Photo 4. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09173 | Date: 11/30/2020

Inspection Photos



Photo 5. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09173 | Date: 11/30/2020

Inspection Photos



Photo 6. Facing toward the TA well. The well does not appear to have be in use since 3/1/2008.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09173 | Date: 11/30/2020