

Inspection Photos

API: 071-07049

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/30/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07049 | Date: 11/30/2020

Inspection Photos



Photo 1. There is erosion along the access road and the culvert is filled in with sediment shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07049 | Date: 11/30/2020

Inspection Photos



Photo 2. Facing toward the well. The sign has fallen over and needs to be installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07049 | Date: 11/30/2020