

# Inspection Photos

API: 071-08925

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/30/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08925 | Date: 11/30/2020

## Inspection Photos



**Photo 1.** There is an erosion gully along the access road caused by stormwater directed from the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08925 | Date: 11/30/2020

## Inspection Photos



**Photo 2.** Facing southeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08925 | Date: 11/30/2020



## Inspection Photos



**Photo 3.** Well sign posted at meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08925 | Date: 11/30/2020