

## Inspection Photos

Location Name: PAPPENHEIM-67N64W /26SWSE

Location #: 302874



Colorado Oil & Gas Conservation Commission  
40.53836, -104.51545, 4746.7ft, 296°  
12/01/2020 13:51:01

### Photo #1

Pappenheim 34-26 (05-123-29961) Wellsite

Shut-In | SI

**Company / Well name NOT posted**  
**Emergency number NOT posted at well**



Colorado Oil & Gas Conservation Commission  
40.54199, -104.50785, 4705.9ft, 318°  
12/01/2020 14:34:35

### Photo #2

Pappenheim 43-26, 33-26, 34-26, 44-26 Battery site

Inactive | Shut-down.