

Inspection Photos  
Location Name: Vernon Grady 12-20  
Location ID: 320461



Photo #1 Tanks.

Photo #2 Separator.

Inspection Photos  
Location Name: Vernon Grady 12-20  
Location ID: 320461



Photo #3 Well Head.

Photo #4 trash on location.

Inspection Photos  
Location Name: Vernon Grady 12-20  
Location ID: 320461




Photo #5 Berms broken down by wild life.

Photo #6 Berms broken down by wild life.

Inspection Photos  
Location Name: Vernon Grady 12-20  
Location ID: 320461



**Photo #7 Berms broken down by wild life.**

**Photo #8 stained soil around Separator.**