

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/01/2020

Submitted Date:

12/03/2020

Document Number:

700600230

**FIELD INSPECTION FORM**

Loc ID 321920 Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10634  
Name of Operator: P O & G OPERATING LLC  
Address: 5847 SAN FELIPE SUITE 3200  
City: HOUSTON State: TX Zip: 77057

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Mel		mel_smith@pogresources.com	
Colotta, Wendy	281-620-1993	wendy_colotta@pogresources.com	Production & Regulatory Associate

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208528	WELL	PR	06/01/2020	OW	017-07463	HOFFMAN 5	EI

**General Comment:**

This is an environmental inspection to document status of remediation 13683. Analytical results show remediation area is compliant with COGCC Table 910-1 and is ready for seeding. Operator will seed in spring 2021.

Crude oil was found just off the east side of the well pad. Crude oil appears to have been dumped into an animal burrow. See attached photos and corrective action.

**Inspected Facilities**

Facility ID: 208528 Type: WELL API Number: 017-07463 Status: PR Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: OIL Estimated Spill Volume: 0.5  
 Comment: Crude oil dumped just off east side of well pad into an animal burrow. See attached photos.  
 Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Date: 01/04/2021  
 Reportable: NO GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_  
 Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700600231	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5302091">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5302091</a>