

Inspection Photos
Location Name: Nichols Tank Battery 10-6
Location ID: 422472



Photo 1 Stained soil has been removed



Photo 2 possible leak appears to have been addressed or isolated.