

Inspection Photos

Loc#467526

Operator: Sandridge

Insp#: 692402703

Insp Date: 11/19/20





Photo#1:
Overview of Location to Southwest.

November 19, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Spicer Annex Loc#467526



Photo#2:
Weedy Reclamation area.



Photo#3:
Weedy Reclamation area and topsoil stockpile.

November 19, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Spicer Annex Loc#467526



Photo#4:
BMP at Northeast Corner.



Photo#5:
Receiving area BMP in Photo#4

November 19, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Spicer Annex Loc#467526