

Inspection Photos
Location Name: State Seventy Holes 21-6 PAD
Location ID: 438056



Photo 1 – Tank Battery



Photo 2 – Separators

Inspection Photos
Location Name: State Seventy Holes 21-6 PAD
Location ID: 438056



Photo 3 – Tank Battery Sign



Photo 4 – Wellheads

Inspection Photos
Location Name: State Seventy Holes 21-6 PAD
Location ID: 438056



Photo 5 – Maintenance Tank



Photo 6 – Risers at Rack now Marked

Inspection Photos
Location Name: State Seventy Holes 21-6 PAD
Location ID: 438056



Photo 7 – Risers at Separators now Marked



Photo 8 – Unused Down Hole Tools at North end of Wellheads

Inspection Photos
Location Name: State Seventy Holes 21-6 PAD
Location ID: 438056



Photo 9 – Stained Soil at F11 –J14-6 HNC Wellhead



Photo 10 – Wellhead Sign

Inspection Photos
Location Name: State Seventy Holes 21-6 PAD
Location ID: 438056



Photo 11 – Stained Soil at A-E-6 HNB Wellhead



Photo 12 – Wellhead Sign

Inspection Photos
Location Name: State Seventy Holes 21-6 PAD
Location ID: 438056



Photo 13 – Stained Soil at A-E-6 HNB Wellhead



Photo 14 – Stained Soil at A-E-6 HNB Wellhead

Inspection Photos
Location Name: State Seventy Holes 21-6 PAD
Location ID: 438056



Photo 15 – Containment – Oily Waste and Wildlife Netting in disrepair



Photo 16 – Containment – Oily Waste and Wildlife Netting in disrepair

Inspection Photos
Location Name: State Seventy Holes 21-6 PAD
Location ID: 438056



Photo 17 – Stained Soil at Rack



Photo 18 – Stained Soil at Rack