

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402539347

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: HIGHPOINT OPERATING CORPORATION	Operator No: 10071	Phone Numbers Phone: (303) 3128718 Mobile: (303) 5182290
Address: 555 17TH ST STE 3700		
City: DENVER	State: CO Zip: 80202	
Contact Person: Rusty Frishmuth	Email: rfrishmuth@hpres.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 15965

Initial Form 27 Document #: 402479217

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input checked="" type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input checked="" type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: LOCATION	Facility ID: 330502	API #:	County Name: WELD
Facility Name: UPRC FEDERAL-610N64W 23NWNW		Latitude: 40.825681	Longitude: -104.521787
		** correct Lat/Long if needed: Latitude: 40.826293	Longitude: -104.522000
QtrQtr: NWNW	Sec: 23	Twp: 10N	Range: 64W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SP

Most Sensitive Adjacent Land Use Range

Is domestic water well within 1/4 mile? No

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Willow Creek is located approximately 490 feet south of the water tank and vault.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☐ Oil ☐ Tank Bottoms
- ☐ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	30	soil samples

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A partially buried 100 bbl produced water tank and adjacent concrete vault were removed during P&A activities. Following removal of the water tank and concrete vault, On October 14, 2020, WSP personnel screened each side wall of both vessels for VOC concentration using a PID detector and was observed for potential petroleum hydrocarbon impact such as staining and/or odor. At both vessels, one grab soil sample was collected from the sidewall exhibiting the highest VOC concentration and/or greatest evidence of potential hydrocarbon impact. Additionally, one grab soil sample was collected from the floor of each tank grave. Samples were collected per USEPA methods and strict chain-of-custody standards will be followed. The soil samples were submitted to an Summit Scientific (Summit) of Golden Colorado for analysis of benzene, toluene, ethylbenzene, and xylene (BTEX), and total petroleum hydrocarbons (TPH)-gasoline range organic (GRO) by USEPA 8260C, TPH-diesel range organics (DRO) and TPH- oil range organics (ORO) by USEPA Method 8015C. The floor soil samples were also submitted for analysis of pH by USEPA Method 9045D, specific conductance (EC) by USEPA Method 9050A, and sodium adsorption ration (SAR) by USDA Agricultural Handbook 60 method (20B). Laboratory analytical results indicated that SS01@3' exceeded the COGCC Table 910-1 standard for TPH at a concentration of 2,701 mg/kg and SS02@4' exceeded the COGCC Table 910-1 standard for pH at 9.43 All other analytical results were compliant with applicable COGCC Table 910-1 standards. The sample locations are shown on the attached figure.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

On November 5, 2020, WSP oversaw excavation of the concrete vault grave where TPH and pH impact was previously identified in SS01@3' and SS02@4', respectively. Additional soil samples (SS02@5' and SS05@3') were collected to confirm the removal of prior impacts. Soil sample SS05@3' was submitted to Summit for analysis of BTEX, and TPH-GRO by USEPA 8260C, TPH-DRO and TPH-ORO by USEPA Method 8015C. Soil sample SS02@5' was submitted to summit for analysis of pH by USEPA Method 9045D. All analytical results were compliant with applicable COGCC table 910-1 standards. The locations and analytical data are summarized on the attachments.

Proposed Groundwater Sampling

☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater not encountered.

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 6

Number of soil samples exceeding 910-1 2

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 50

NA / ND

-- Highest concentration of TPH (mg/kg) 2701

-- Highest concentration of SAR 7.89

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 0

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) 0'

Number of groundwater monitoring wells installed 0

Number of groundwater samples exceeding 910-1 0

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

0 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Impacted material was removed via excavation verified by confirmation soil samples.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Impacted material was removed via excavation verified by confirmation soil samples.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

☒ Ex Situ

Yes _____ Excavate and offsite disposal

If Yes: Estimated Volume (Cubic Yards) _____ 6

Name of Licensed Disposal Facility or COGCC Facility ID # _____

_____ Excavate and onsite remediation

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

☐ _____ Bioremediation (or enhanced bioremediation)

☐ _____ Chemical oxidation

☐ _____ Air sparge / Soil vapor extraction

☐ _____ Natural Attenuation

☐ _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☒ Other once

Report Type: ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report

☒ Other Soil Sampling Results Summary Report

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

None.

Volume of E&P Waste (solid) in cubic yards 6

E&P waste (solid) description Petroleum impacted soil

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility: Waste Management N. Colorado
landfill Ault CO

Volume of E&P Waste (liquid) in barrels 0

E&P waste (liquid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes

Do all soils meet Table 910-1 standards? Yes

Does the previous reply indicate consideration of background concentrations? No

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface?

Does Groundwater meet Table 910-1 standards? Yes

Is additional groundwater monitoring to be conducted? No

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Location has been reclaimed in accordance with COGCC 1000 series rules. Site was regraded and seeded in November 2020.

Is the described reclamation complete? Yes

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☒ Final?

Did the Surface Owner approve the seed mix? Yes

If NO, does the seed mix comply with local soil conservation district recommendations? Yes

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 09/28/2020

Date of commencement of Site Investigation. 10/13/2020

Date of completion of Site Investigation. 10/13/2020

REMEDIAL ACTION DATES

Date of commencement of Remediation. 11/05/2020

Date of completion of Remediation. 11/05/2020

SITE RECLAMATION DATES

Date of commencement of Reclamation. 11/09/2020

Date of completion of Reclamation. 12/23/2020

OPERATOR COMMENT

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Rusty Frishmuth

Title: EHS Director

Submit Date: _____

Email: rfrishmuth@hpres.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

Remediation Project Number: 15965

COA Type

Description

--	--

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

402540866	ANALYTICAL RESULTS
402540867	ANALYTICAL RESULTS
402540868	ANALYTICAL RESULTS
402540870	SITE MAP

Total Attach: 4 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)