

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /18SWNE

Location ID: 334316



**Photo #2400 from entrance to location.**



**Photo #2401 Sediment is being transported off of location due to tracking and lack of stabilization.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /18SWNE

Location ID: 334316



**Photo #2402 Sediment is being transported off of location due to tracking and lack of stabilization.**