

**Inspection Photos**  
**Location Name: Ford Family Trust 2H**  
**Location ID: 428441**



**Photo 1 – Tank Battery**



**Photo 2 – Heater Treater**

**Inspection Photos**  
**Location Name: Ford Family Trust 2H**  
**Location ID: 428441**



Colorado Oil and Gas Conservation Commission  
40.52444, -104.03228, 4853.0ft, 135°  
12/01/2020 11:36:16




Colorado Oil and Gas Conservation Commission  
40.52519, -104.0307, 4852.6ft, 240°  
12/01/2020 11:35:22

**Photo 3 – Tank Battery Sign at Entrance**

**Photo 4 – Pumping Unit**


**Inspection Photos**  
**Location Name: Ford Family Trust 2H**  
**Location ID: 428441**



**Photo 5 – Stained Soil at Wellhead**

**Photo 6 – Unused belts in NE Corner**

**Inspection Photos**  
**Location Name: Ford Family Trust 2H**  
**Location ID: 428441**



**Photo 7 – Unused Rods and Belts at Pumping Unit**

**Photo 8 – Unused Supply Pot and 1” pipe**

**Inspection Photos**  
**Location Name: Ford Family Trust 2H**  
**Location ID: 428441**



**Photo 9 – Stained Soil at Flare**

**Photo 10 – Stained Soil at Flare**

**Inspection Photos**  
**Location Name: State Seventy Holes 21-6 PAD**  
**Location ID: 438056**



**Photo 11 – Wellhead Sign does not reflect current Operator**

**Photo 12 – Unused Latrine at Entrance**

**Inspection Photos**  
**Location Name: Ford Family Trust 2H**  
**Location ID: 428441**



Colorado Oil and Gas Conservation Commission  
40.52519, -104.03089, 4896.3ft, 302°  
12/01/2020 11:31:11



Colorado Oil and Gas Conservation Commission  
40.52475, -104.03062, 4871.8ft, 268°  
12/01/2020 11:34:48

**Photo 13 – Stained Soil cleaned and Wildlife netting installed**

**Photo 14 – Stained Soil cleaned and Wildlife netting installed**