

Inspection Photos

Operator: Holcomb Operating
API: 067-06543
Date: 12/1/2020



Photo 1. View of the norther project area from the northeastern corner facing westward.



Photo 2. View of the project area from the northeastern corner facing center. Teardrop is revegetating, and vegetation is mowed. Species observed include smooth brome, western wheatgrass, and sand dropseed.



Photo 3. View of the eastern project area from the northeastern corner facing southward. Reference area is comprised of grass field similar to reference area, and sagebrush shrubland mosaic.



Photo 4. View of reference area vegetation comprised of sagebrush shrubland with understory of grasses and forbs such as blue grama, prickly pear, western wheatgrass, and snakeweed.



Photo 4. View of reference area vegetation comprised of pinyon and juniper woodland with gambel oak, sagebrush, and and antelope bitterbrush shrubs, along with *Heterotheca villosa*, western wheatgrass, sand dropseed, and Indian ricegrass in the understory.




Photo 6. View of closed gate after leaving location