

Inspection Photos  
Spill ID 463345  
Remediation Project 12865  
Inspection Date: 12/3/2020  
All Photos taken by Kris Neidel



Photo #1 Area of SB-03 from project files. The area of remaining impact was iced over, flowing water was present below ice.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Spill ID 463345  
Remediation Project 12865  
Inspection Date: 12/3/2020  
All Photos taken by Kris Neidel



Photo #2 Vermillion Creek. Area of SB-03 from project files. The area of remaining impact was iced over, flowing water was present below ice.

