

# *Inspection Photos*

*Loc#313240*

*Operator: Argali*

*Insp#: 692402753*

*Insp Date: 11/20/2020*





Photo#1:

Overview of Location to West. Insert is Wellhead with a few Debris weeds growing in and around equipment.

November 20, 2020



Photo#2:

View of Interim Reclamation to South. Insert, Anchor Markers not bright color and more than 1 ft East of Anchor (in this case 8 ft).

November 20, 2020