

**Inspection Photos**  
**Location Name: Sifkin 11-30H**  
**Location ID: 424135**



**Photo 1 – Tank Battery**




**Photo 2 – Separator, ECD and Flare**

Inspection Photos  
Location Name: Sifkin 11-30H  
Location ID: 424135



Colorado Oil and Gas Conservation Commission  
40.55201, -104.25801, 4760.8ft, 298°  
12/01/2020 13:51:01



Colorado Oil and Gas Conservation Commission  
40.55145, -104.25821, 4770.6ft, 324°  
12/01/2020 13:50:32

Photo 3 – Tank Battery Sign

Photo 4 – Wellhead


**Inspection Photos**  
**Location Name: Sifkin 11-30H**  
**Location ID: 424135**



**Photo 5 – Stained Soil at Exhaust**

**Photo 6 – Stained Soil at Gas Engine**

**Inspection Photos**  
**Location Name: Sifkin 11-30H**  
**Location ID: 424135**



Colorado Oil and Gas Conservation Commission

**Photo 7 – Gas Meter Calibration Card**