

Inspection Photos
Location Name: Wells Ranch USX AA #11-07
Location ID: 310810



Photo 1 Well head.



Photo 2 Unused equipment: PU, PU motor and house and fencing.