

# Inspection Photos

12/4/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 312527

MesaCounty, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312527



**Photo 1:** Photo taken from the location entrance, facing southeast. Photo shows access road and Location. Compaction evident at access road. Reclamation of Location and access road not progressing towards 1004 standards.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312527



**Photo 2:** Photo taken from the northwest corner of the Location, facing east. Photo shows reclamation of the Location is not progressing towards 1004 standards; Insufficient desirable vegetative germination and establishment. Location predominantly bare/exposed soils.





## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312527



**Photo 3:** Photo taken from the northwest corner of the Location, facing south. Photo shows reclamation of the Location is not progressing towards 1004 standards; Insufficient desirable vegetative germination and establishment. Location predominantly bare/exposed soils.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312527



**Photo 4:** Photo taken from the southwest corner of the Location, facing north. Photo shows reclamation of the Location is not progressing towards 1004 standards; Insufficient desirable vegetative germination and establishment. Location predominantly bare/exposed soils.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312527



**Photo 5:** Photo taken from the southwest corner of the Location, facing east. Photo shows reclamation of the Location is not progressing towards 1004 standards; Insufficient desirable vegetative germination and establishment. Location predominantly bare/exposed soils.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312527



**Photo 6:** Photo taken from the Location. Photo shows desirable perennial vegetative germination and establishment is insufficient. Location is not progressing towards 1004 reclamation standards.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312527



**Photo 7:** Photo taken from the access road. Unable to find evidence that compaction alleviation has been conducted at access road. Insufficient desirable vegetative germination and establishment. Access road predominantly bare/exposed soils.

