

# Inspection Photos

12/4/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 312644

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312644



**Photo 1:** Photo taken from the south end of the Location, facing west. Photos 1-3 provide an overview of the Location from west, north to east.

**Inspection Photos**  
**Operator Name: CAERUS PICEANCE LLC - 10456**  
**Location ID: 312644**



**Photo 2:** See comments under photo 1.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312644



**Photo 3:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312644



**Photo 4:** Photo taken from the northwest corner of the tank battery. Photo shows fence panel in disrepair. Livestock access within containment berm evident. Advise maintenance to restrict livestock access to battery and containment BMP.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312644



**Photo 5:** Photo taken from the southeast corner of the Location, facing west. Photo shows example of anchor missing proper marking.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312644



**Photo 6:** Photo taken from the southwest corner of the Location, facing west. Photo shows example of anchor missing proper marking.