

Inspection Photos

12/4/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 312637

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312637



Photo 1: Photo taken from the southeast corner of the Location, facing west. Photos 1-3 provide an overview of the Location from west, northwest to north. Photos shows final reclamation, including but not limited to, compaction alleviation, recontouring/regrading and revegetation activities have not been performed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312637



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312637



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312637



Photo 4: Photo shows anchor equipment remaining on the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312637



Photo 5: Photo shows anchor and pipe equipment remaining on the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312637



Photo 6: Photo taken from the northwest corner of the Location, facing northwest. Photo shows pit has not been backfilled/reclaimed. Gravel remaining.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312637



Photo 7: Photo taken from the northwest corner of the Location, facing east. Photos 7-9 provide an overview of the Location from east, southeast to south. Photos shows final reclamation, including but not limited to, compaction alleviation, recontouring/regrading and revegetation activities have not been performed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312637



Photo 8: See comments under photo 7.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312637



Photo 9: See comments under photo 7.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312637



Photo 10: Photo taken from the southwest of the Location, facing northeast. Photo shows recontouring/regrading of the Location to its original, relative position has not been performed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312637



Photo 11: Photo taken from the access road northeast of the Location, facing southwest. Photo shows access road has not been reclaimed.