

Inspection Photos

Location Name: Cascade Creek 609-33 pad

Location ID: #335801

Inspection Date: December 4, 2020



Photo #1 – Tank battery sign.




Photo #2 – Salt-stained gravel beneath tank battery loadout.

Inspection Photos

Location Name: Cascade Creek 609-33 pad

Location ID: #335801

Inspection Date: December 4, 2020



Photo #3 – Separators.



Photo #4 – View of wellheads from northeast.



Inspection Photos

Location Name: Cascade Creek 609-33 pad

Location ID: #335801

Inspection Date: December 4, 2020



Photo #5 – View into well cellar, northwest corner, no wildlife egress was observed in this location.



Photo #6 - View into well cellar, southeast corner, no wildlife egress was observed in this location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources