

Inspection Photos

API: 071-07640

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/4/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07640 | Date: 12/4/2020

Inspection Photos



Photo 1. Erosion along the access road has been repaired and stabilized with rock.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07640 | Date: 12/4/2020

Inspection Photos



Photo 2. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07640 | Date: 12/4/2020

Inspection Photos



Photo 3. The pit liner has been replaced and fence around the pit is maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07640 | Date: 12/4/2020