

Inspection Photos

API: 071-09212

Operator: OGRIS OPERATING LLC

Inspection Date: 12/4/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09212 | Date: 12/4/2020

Inspection Photos



Photo 1. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09212 | Date: 12/4/2020

Inspection Photos



Photo 2. Facing southeast toward the interim reclamation area. Vegetation is well established and location stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09212 | Date: 12/4/2020

Inspection Photos



Photo 3. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09212 | Date: 12/4/2020