

Inspection Photos
Location Name: Reines 1-1
Location ID: 427144



Photo 1 – Tank Battery



Photo 2 – East Crude Oil Tank missing

Inspection Photos
Location Name: Reines 1-1
Location ID: 427144



Photo 3 – ECD and Flare



Photo 4 – Stained Soil at Wellhead



Inspection Photos
Location Name: Reines 1-1
Location ID: 427144



Photo 5 – Wellhead



Photo 6 – Gas Engine – Stained Soil



Inspection Photos
Location Name: Reines 1-1
Location ID: 427144



Photo 7 – Stained Soil at Gas Engine



Photo 8 – Tank Battery Sign

