

Inspection Photos
Location Name: Loomis 2-1H PAD
Location ID: 438327



Photo 1 – Signs at Entrance



Photo 2 – Wells



Inspection Photos
Location Name: Loomis 2-1H PAD
Location ID: 438327




Photo 3 – Unused Equipment and Parts




Photo 4 – Unused Parts

Inspection Photos
Location Name: Loomis 2-1H PAD
Location ID: 438327



Photo 5 – Stained Soil at 2-3H Exhaust



Photo 6 – Flare – Stained Soil at 2-3H Gas Engine

Inspection Photos
Location Name: Loomis 2-1H PAD
Location ID: 438327



Photo 7 – Stained Soil at 2-3H Wellhead




Photo 8 – Stained Soil at 2-6H Wellhead

Inspection Photos
Location Name: Loomis 2-1H PAD
Location ID: 438327



Photo 9 – Stained Soil at 2-1H Supply Pot



Photo 10 – Stained Soil at 2-1H Wellhead

Inspection Photos
Location Name: Loomis 2-1H PAD
Location ID: 438327



Photo 11 – Stained Soil at 2-1H Wellhead



Photo 12 – Day Tank at Compressor missing Wildlife Netting



Inspection Photos
Location Name: Loomis 2-1H PAD
Location ID: 438327



Photo 13 – Stained Soil at Compressor



Photo 14 – Unused at Compressor

Inspection Photos
Location Name: Loomis 2-1H PAD
Location ID: 438327



Photo 15 – Stained Soil at Compressor and Unused Parts



**Photo 16 – Drain Vault at Compressor missing Lables –
Content, Capacity and NFPA**

Inspection Photos
Location Name: Loomis 2-1H PAD
Location ID: 438327



Photo 17 – Heater Treaters



Photo 18 – West Heater Treater appears to be missing Bird Screen Protector

Inspection Photos
Location Name: Loomis 2-1H PAD
Location ID: 438327



Photo 19 – Gas Meters



Photo 20 – Tank Battery



Inspection Photos
Location Name: Loomis 2-1H PAD
Location ID: 438327



Photo 21 – Tank Battery



Photo 22 – ECD and Flare