

Inspection Photos


API#081-05370

Operator: Kaiser-Francis

Insp#: 692402709

Insp Date: 11/20/2020





Photo#1:

Overview of Location to West. Note Anchor marker in foreground, not a bright color.

November 20, 2020



Photo#2:
Birds nest in pump Jack.

November 20, 2020