

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402538416

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP	Operator No: 47120	Phone Numbers Phone: (970) 336-3500 Mobile: (970) 515-1161
Address: P O BOX 173779		
City: DENVER	State: CO Zip: 80217-3779	
Contact Person: Phillip Hamlin	Email: Phillip_Hamlin@oxy.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 15687

Initial Form 27 Document #: 402433337

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input checked="" type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: SPILL OR RELEASE	Facility ID: 476912	API #:	County Name: ADAMS
Facility Name: SPILL/RELEASE POINT		Latitude: 39.928355	Longitude: -104.674644
		** correct Lat/Long if needed: Latitude:	Longitude:
QtrQtr: NWNW	Sec: 33	Twp: 1S	Range: 65W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications CL

Most Sensitive Adjacent Land Use Crop Land

Is domestic water well within 1/4 mile? No

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

None

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☒ Oil ☐ Tank Bottoms
- ☒ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	See attached data	Groundwater sampling and laboratory analysis
Yes	SOILS	28' (N-S) x 25' (E-W) x 11.5' bgs	Excavation, soil sampling, and laboratory analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Historical impacts were discovered during reclamation activities at the HSR-Van Schaack 4-33 production facility, and excavation activities were initiated. On June 12, 2020, groundwater was encountered in the excavation area at approximately 9.5 feet below ground surface (bgs); groundwater was subsequently observed at 5 feet bgs while excavation activities were ongoing. The COGCC issued Spill/Release Point ID 476912 for this release.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Soil samples were collected as described in the Initial Form 27 (COGCC Document No. 402433337). Based on the data presented, impacted soils in the excavation area were remediated to be in full compliance with the COGCC Table 910-1 standards.

Proposed Groundwater Sampling

☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

On October 28, 2020, five (5) temporary groundwater monitoring wells (BH01 - BH05) were installed to further assess the extent of potential remaining groundwater impacts. Quarterly groundwater monitoring was initiated on November 12, 2020, and is ongoing. Groundwater samples are collected from the temporary groundwater monitoring wells on a quarterly basis and analyzed for benzene, toluene, ethylbenzene, and total xylenes (BTEX). Groundwater analytical data is presented in Table 1, and the groundwater sample locations are illustrated on Figure 1. The laboratory analytical report for the Fourth Quarter 2020 groundwater sampling event is provided as Attachment A.

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 6
Number of soil samples exceeding 910-1 1
Was the areal and vertical extent of soil contamination delineated? Yes
Approximate areal extent (square feet) 700

NA / ND

-- Highest concentration of TPH (mg/kg) 295
-- Highest concentration of SAR 2.92
BTEX > 910-1 Yes
Vertical Extent > 910-1 (in feet) 11

Groundwater

Number of groundwater samples collected 7
Was extent of groundwater contaminated delineated? Yes
Depth to groundwater (below ground surface, in feet) 5'
Number of groundwater monitoring wells installed 5
Number of groundwater samples exceeding 910-1 1

-- Highest concentration of Benzene (µg/l) 296
-- Highest concentration of Toluene (µg/l) 381
-- Highest concentration of Ethylbenzene (µg/l) 762
-- Highest concentration of Xylene (µg/l) 5780
NA Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected
0 Number of surface water samples exceeding 910-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) Volume of liquid waste (barrels)

☒ Is further site investigation required?

The 5 temporary groundwater monitoring wells (BH01 - BH05) will continue to be sampled on a quarterly basis and submitted for laboratory analysis of BTEX until concentrations remain in full compliance with the COGCC Table 910-1 standards for four consecutive quarters.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Between June 12 and 15, 2020, approximately 330 cubic yards of impacted material were excavated and transported to the Buffalo Ridge Landfill in Keenesburg, Colorado for disposal. Between June 12 and 16, 2020, approximately 795 barrels of groundwater were removed from the excavation area via vacuum truck and transported to the Kerr-McGee Aggregate Recycle Facility in Weld County, Colorado for recycling.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Laboratory analytical results indicate that impacted soils in the excavation area have been remediated to be in full compliance with the COGCC Table 910-1 standards. Prior to backfilling, approximately 165 pounds of OxPure® activated carbon were added to the groundwater within the excavation area to mitigate potential remaining hydrocarbon impacts in groundwater. Quarterly groundwater monitoring is ongoing and will be continued until concentrations remain in full compliance with the COGCC Table 910-1 standards for four consecutive quarters. Additional remedial activities may be evaluated, as necessary, to address potential remaining groundwater impacts. Estimated time to attain NFA is TBD based on the groundwater concentrations, the extent of impacted groundwater, and the efficacy of the selected remedial technologies.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

☒ Ex Situ

Yes Excavate and offsite disposal
_____ If Yes: Estimated Volume (Cubic Yards) 330
Name of Licensed Disposal Facility or COGCC Facility ID # _____
Excavate and onsite remediation
_____ Land Treatment
_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

No Bioremediation (or enhanced bioremediation)
No Chemical oxidation
No Air sparge / Soil vapor extraction
Yes Natural Attenuation
Yes Other Groundwater removal, OxPure®
activated carbon application

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

On October 28, 2020, 5 temporary groundwater monitoring wells (BH01 - BH05) were installed to further assess the extent of potential remaining groundwater impacts. The temporary groundwater monitoring wells will continue to be sampled on a quarterly basis and submitted for laboratory analysis of BTEX until concentrations remain in full compliance with the COGCC Table 910-1 standards for four consecutive quarters. Groundwater sample locations and a potentiometric surface contour map for the Fourth Quarter 2020 are illustrated on Figure 1. Well completion logs for the temporary monitoring wells are provided as Attachment B.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☒ Quarterly ☐ Semi-Annually ☐ Annually ☐ Other _____

Report Type: ☒ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report

☐ Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Approximately 795 barrels of hydrocarbon-impacted groundwater were transported to the Kerr-McGee Aggregate Recycle Facility in Weld County, Colorado for recycling.

Volume of E&P Waste (solid) in cubic yards _____ 330

E&P waste (solid) description _____ Hydrocarbon-impacted soil

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: Buffalo Ridge Landfill - Keenesburg, Colorado

Volume of E&P Waste (liquid) in barrels _____ 795

E&P waste (liquid) description _____ Hydrocarbon-impacted groundwater

COGCC Disposal Facility ID #, if applicable: _____ 434766

Non-COGCC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No _____

Do all soils meet Table 910-1 standards? Yes _____

Does the previous reply indicate consideration of background concentrations? No _____

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? _____

Does Groundwater meet Table 910-1 standards? Yes _____

Is additional groundwater monitoring to be conducted? Yes _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The site has been restored to its pre-release grade. Kerr-McGee will conduct reclamation activities in accordance with COGCC 1000 Series Rules.

Is the described reclamation complete? No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 06/12/2020

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 06/12/2020

Date of commencement of Site Investigation. 06/12/2020

Date of completion of Site Investigation. _____

REMEDIAL ACTION DATES

Date of commencement of Remediation. 06/12/2020

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

Points-of-compliance (POC) have been established, and future Form 27-Supplemental updates will be submitted to the COGCC on an annual basis.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Phillip Hamlin

Title: Senior Environmental Rep

Submit Date: _____

Email: Phillip_Hamlin@oxy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

Remediation Project Number: 15687

COA Type

Description

--	--

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

402538450	LOGS
402538451	GROUND WATER ELEVATION MAP
402538452	ANALYTICAL RESULTS
402546155	ANALYTICAL RESULTS

Total Attach: 4 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)