

Inspection Photos
Location Name: Guttersen D 29-20 Pad
Location ID: 457653



Photo #1 Producing Wells




Photo #2 Waiting to be drilled



Inspection Photos
Location Name: Guttersen D 29-20 Pad
Location ID: 457653



Photo #3 Unused Frac Tanks



Photo #4 Unused Frac Tanks