

Inspection Photos  
Location Name: Zimmerman Pad  
Location ID: 332964




Photo 1: Wellhead Sign



Photo 2: Stained soil removed

**Inspection Photos**  
**Location Name: Zimmerman Pad**  
**Location ID: 332964**



**Photo 3: Disconnected gas meter removed**