

Inspection Photos
Operator: BP America
API: 067-09471
Date: 12/7/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope, facing westward. Revegetation is progressing with crested wheatgrass, western wheatgrass, and sand dropseed.



Photo 3. View of the reference area comprised of sagebrush shrubland and pinyon/juniper woodland with understory of squirreltail, blue grama, and penstemon spp.