

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 324270



**Photo #2409 from entrance to location.**



**Photo #1981 from inspection #699801878 inspection conducted on 10/2/20.**



## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 324270



**Photo #2410 Multiple places with weeds and debris on location.**



**Photo #1982 from inspection #699801878 inspection conducted on 10/2/20.**



## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /14NENE

Location ID: 324270



**Photo #2411 Secondary containment not adequate weeds and debris inside tank containment.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources