

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /24SWNE

Location ID: 312609



Photo #2415 from entrance to location.



Photo #2416 from entrance to location.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /24SWNE

Location ID: 312609



Photo #2052 from inspection #699801952 conducted 10/19/20.



Photo #2417 unused equipment.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /24SWNE

Location ID: 312609



Photo #2053 from inspection #699801952 conducted 10/19/20.



Photo #2418 Vegetation growing on secondary containment.