

Grizzly Operating Anchondo Location # 335119

Dec 9, 2020 at 1:53:58 PM
39.514761,-107.685623 ±4.38m
COGCC



location

Dec 9, 2020 at 1:53:36 PM
39.514688,-107.685721 ±26.87m
COGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Anchondo Location # 335119

Dec 9, 2020 at 1:54:30 PM
39.514769,-107.685364 ±4.77m
COGCC



location

Dec 9, 2020 at 1:58:48 PM
39.514636,-107.685131 ±4.80m
COGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Anchondo Location # 335119



location



Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Anchondo Location # 335119



Lack of stabilization



Lack of stabilization



Grizzly Operating Anchondo Location # 335119



Lack of stabilization



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources