

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/08/2020

Submitted Date:

12/09/2020

Document Number:

696202108**FIELD INSPECTION FORM**

Loc ID 383264 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
383264	LOCATION	AC			-	CC 0610-21-41 Pad	RI
461989	WELL	XX	02/13/2019		045-24253	CC 0697-10-05E	RI
461990	WELL	XX	02/13/2019		045-24254	CC 0697-10-02E	RI
461991	WELL	XX	02/13/2019		045-24255	CC 0697-10-06W	RI
461992	WELL	XX	02/13/2019		045-24256	CC 0697-10-01E	RI
461993	WELL	XX	02/13/2019		045-24257	CC 0697-10-07E	RI
461994	WELL	XX	02/13/2019		045-24258	CC 0697-10-06E	RI
461995	WELL	XX	02/13/2019		045-24259	CC 0697-10-03E	RI
461996	WELL	XX	02/13/2019		045-24260	CC 0697-10-05W	RI
461997	WELL	XX	02/13/2019		045-24261	CC 0697-10-04W	RI
461998	WELL	XX	02/13/2019		045-24262	CC 0697-10-02W	RI
461999	WELL	XX	02/13/2019		045-24263	CC 0697-10-01W	RI
462000	WELL	XX	02/13/2019		045-24264	CC 0697-10-03W	RI
462002	WELL	XX	02/13/2019		045-24266	CC 0697-10-04E	RI
462003	WELL	XX	02/13/2019		045-24267	CC 0697-10-08W	RI
462011	WELL	XX	02/13/2019		045-24268	CC 0697-10-SWD1	RI

General Comment:

On 12/08/2020, Reclamation Specialist Trujillo conducted reclamation inspection at Laramie Energy's CC 0610-21-41 Pad location in Garfield County, Colorado.

This following compliance issues were observed during the inspection:

34-60-121(1) CRS-b: Permit Violation

1003/1004: Interim and Final Reclamation

Refer to the "Reclamation" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities				
Facility ID:	<u>383264</u>	Type:	<u>LOCATION</u>	API Number: <u>-</u> Status: <u>AC</u> Insp. Status: <u>RI</u>
Facility ID:	<u>461989</u>	Type:	<u>WELL</u>	API Number: <u>045-24253</u> Status: <u>XX</u> Insp. Status: <u>RI</u>
Facility ID:	<u>461990</u>	Type:	<u>WELL</u>	API Number: <u>045-24254</u> Status: <u>XX</u> Insp. Status: <u>RI</u>
Facility ID:	<u>461991</u>	Type:	<u>WELL</u>	API Number: <u>045-24255</u> Status: <u>XX</u> Insp. Status: <u>RI</u>
Facility ID:	<u>461992</u>	Type:	<u>WELL</u>	API Number: <u>045-24256</u> Status: <u>XX</u> Insp. Status: <u>RI</u>
Facility ID:	<u>461993</u>	Type:	<u>WELL</u>	API Number: <u>045-24257</u> Status: <u>XX</u> Insp. Status: <u>RI</u>
Facility ID:	<u>461994</u>	Type:	<u>WELL</u>	API Number: <u>045-24258</u> Status: <u>XX</u> Insp. Status: <u>RI</u>
Facility ID:	<u>461995</u>	Type:	<u>WELL</u>	API Number: <u>045-24259</u> Status: <u>XX</u> Insp. Status: <u>RI</u>
Facility ID:	<u>461996</u>	Type:	<u>WELL</u>	API Number: <u>045-24260</u> Status: <u>XX</u> Insp. Status: <u>RI</u>
Facility ID:	<u>461997</u>	Type:	<u>WELL</u>	API Number: <u>045-24261</u> Status: <u>XX</u> Insp. Status: <u>RI</u>
Facility ID:	<u>461998</u>	Type:	<u>WELL</u>	API Number: <u>045-24262</u> Status: <u>XX</u> Insp. Status: <u>RI</u>
Facility ID:	<u>461999</u>	Type:	<u>WELL</u>	API Number: <u>045-24263</u> Status: <u>XX</u> Insp. Status: <u>RI</u>
Facility ID:	<u>462000</u>	Type:	<u>WELL</u>	API Number: <u>045-24264</u> Status: <u>XX</u> Insp. Status: <u>RI</u>
Facility ID:	<u>462002</u>	Type:	<u>WELL</u>	API Number: <u>045-24266</u> Status: <u>XX</u> Insp. Status: <u>RI</u>
Facility ID:	<u>462003</u>	Type:	<u>WELL</u>	API Number: <u>045-24267</u> Status: <u>XX</u> Insp. Status: <u>RI</u>
Facility ID:	<u>462011</u>	Type:	<u>WELL</u>	API Number: <u>045-24268</u> Status: <u>XX</u> Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Location constructed 2005 by Oxy. Laramie took ownership of Location 3/1/2016. FIRs #680101328 dated 12/14/2016 and #680102390 dated 11/03/2017 required Final Reclamation by 7/1/2017; Operator failed to comply with 1004 Rules and Corrective actions.

Operator permitted new wells on the Location (approved 2/13/2019). Form 2 Permit conditions for wells required that "Operator shall comply with Notice to Operators: Interim Reclamation Procedures for Delayed Operation (dated January 5, 2017)".

It was observed in this inspection that no drilling or subsequent operations have commenced. No "Delayed Operations NTO" request has been submitted or approved per permit COAs.

Operator is out of compliance with Rules and Permit conditions.

Corrective Action

Operator is directed to either immediately:

1) Comply with the "Notice to Operators: Interim Reclamation Procedures for Delayed Operation (dated January 5, 2017)" and permit conditions.

or

2) Perform final reclamation of the Location.

Date **02/13/2019**

Overall Interim Reclamation **Fail**

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80%

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696202109	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5306954