

Final Reclamation Inspection

November 25, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 336344

Inspection Document #: 697502215

Weld County, CO

NWNW Section 26 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: (HSR)ANDERSON #4-26A
Location ID: 336344



Photo 1. Photo taken from the well location, facing Southeast. Photo illustrates the Operator has removed all equipment from the location. Well location is currently within a residential development of the B Bold RV Park.



Inspection Photos
Location Name: (HSR)ANDERSON #4-26A
Location ID: 336344



Photo 2. Photo taken from the well location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: (HSR)ANDERSON #4-26A
Location ID: 336344



Photo 3. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: (HSR)ANDERSON #4-26A
Location ID: 336344



Photo 4. Photo taken from the well location, facing North. See comments under Photo 1.



Inspection Photos
Location Name: (HSR)ANDERSON #4-26A
Location ID: 336344



Photo 5. Photo taken from the well location, facing East. See comments under Photo 1. Note: the well in the Photo is an active well operated by KPK.



Inspection Photos
Location Name: (HSR)ANDERSON #4-26A
Location ID: 336344



Photo 6. Photo taken of the associated offsite tank battery, facing East. Photo illustrates the tank battery is still active and in use for other nearby wells.



Inspection Photos
Location Name: (HSR)ANDERSON #4-26A
Location ID: 336344



Photo 7. Photo taken from the entrance of the residential development of the B Bold RV Park.

