

Final Reclamation Inspection

November 25, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 336348

Inspection Document #: 697502219

Weld County, CO

SWSE Section 22 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STREAR #15-22A
Location ID: 336348



Photo 1. Photo taken from the well location, facing West. Photo illustrates the Operator has removed all equipment from the location. Well location is within a cultivated field which has been planted in winter wheat. The establishment of winter wheat appears reflective of reference areas.



Inspection Photos
Location Name: STREAR #15-22A
Location ID: 336348



Photo 2. Photo taken from the well location, facing North. See comments under Photo 1.



Inspection Photos
Location Name: STREAR #15-22A
Location ID: 336348



Photo 3. Photo taken from the well location, facing East. See comments under Photo 1. Note, this was a shared location with another Operator, KPK.



Inspection Photos
Location Name: STREAR #15-22A
Location ID: 336348



Photo 4. Photo taken from the well location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: STREAR #15-22A
Location ID: 336348



Photo 5. Photo taken from the associated offsite tank battery location. Photo illustrates the tank battery is still active and in use for other nearby wells.

