

Inspection Photos
Operator: BP America
API: 067-06614
Date: 12/7/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing in a grazed condition.



Photo 3. View of the reference area comprised of sagebrush shrubland and pinyon/juniper woodland with understory of squirreltail, blue grama, and penstemon spp.



Photo 5. View of closed gate after leaving location.