

Inspection Photos

12/8/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 323893

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 1: 2019 COGIS aerial image. Photo shows two parallel access roads leading to the CC 0604-1 Pad, and the Cascade Creek 697-04D. This does not comport with Rule 1002.e “surface disturbance minimization” requirements regarding access roads. Roads identified in yellow will require reclamation.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 2: Two access roads travel parallel north and south of one another. Photo shows the access road that travels from the southwestern end of the CC 0604-1 Pad Location, facing south.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 3: Photo taken from the south of the CC 0604-1 Pad Location, facing north. Photo shows the two parallel access roads that travel from the CC 0604-1 Pad Location, and the Cascade Creek 697-04D Location (See photo 1).

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 4: Photo taken from the west end of the Location. Photo shows container stored on location. Equipment not needed for production and requires removal.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



20201208

Photo 5: Photo taken from the west end of the Location. Photo shows container stored on location. Equipment not needed for production and requires removal.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 6: Shows barrel containing “heat transfer fluid” stored on the location. This is not proper materials management; Place barrel into secondary containment, or remove and properly stored.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 7: Photo shows equipment not stored in a workman-like manner.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 8: Photo taken from the north end of the CC 0604-1 Pad Location, facing north. Photo shows the two parallel access roads that travel from the CC 0604-1 Pad Location, and the Cascade Creek 697-04D Location (See photo 1).

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 9: Photo taken from the north end of the CC 0604-1 Pad Location, facing south. There are currently 2 access roads, and 4 access points (on the northwest, northeast, southwest and southeast) to the CC 0604-1 Pad . Photo shows eastern access road

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 10: Photo taken from the southwest corner of the Cascade Creek 697-04D location. Photo shows additional access road leading to the CC 0604-1 Pad. This is additional disturbance that does not comport with Rule 1002.e

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 323893



Photo 11: Photo taken from the south of the CC 0604-1 Pad Location, facing north. Photo shows the two access roads that run parallel to one another to the CC 0604-1 Pad.