

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Gunderson /13-11 Pad

Location ID: 334546



Photo #2430 from entrance to location.



Photo #2431 from entrance to location.

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Gunderson /13-11 Pad

Location ID: 334546



Network time is not synchronize  
Local:Dec 9, 2020 at 12:17:46 PM MS



Network time is not synchronize  
Local:Dec 9, 2020 at 12:18:50 PM MS

**Photo #2432 Sediment is being transported off of location**

**Photo #2433 Sediment is being transported off of location**

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Gunderson /13-11 Pad

Location ID: 334546



**Photo #2434** Sediment is being transported off of location



**Photo #2435** Sediment is being transported off of location

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Gunderson /13-11 Pad

Location ID: 334546



**Photo #2436 Sediment is being transported off of location**



**Photo #2437 Access road.**