

Inspection Photos

Location Name: LARAMIE ENERGY LLC Jensen /19-01 Pad

Location ID: 426451



Photo #2441 from entrance to location.



Photo #2442 Sediment is being transported off of location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Jensen /19-01 Pad

Location ID: 426451



Photo #2443 Sediment is being transported off of location



Photo #2444 Access road.