



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Well after casing cut off below ground level with hood on.**

**Runknown 35-11**

**API: 05-103-12422**

**Inspection: 700404525**





40.09914, -108.85574, 5163.2ft, 360°  
11/19/2020 11:35:19 AM





40.09916, -108.85572, 5145.8ft, 329°  
12/08/2020 04:34:07 PM














40.09911, -108.85564, 5142.0ft, 313°  
12/10/2020 01:48:59 PM





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 7. FLIR image with HSM before 3' plug added.

Runkown 35-11

API: 05-103-12422

Inspection: 700404525