



- Photo 1 – View north across former pit/landfarm area (south of well 121-07074).



- Photo 2 – View east across toward corrals visible on aerial photos



- Photo 3 – Remnant oily soils in landfarm area



- Photo 4 – Remnant oily soils in landfarm area



- Photo 5 – Remnant oily soils and junk in landfarm area



- Photo 6 – Remnant oily soils in landfarm area



- Photo 7 – View northeast across remnant oily soils in landfarm area



- Photo 8 – View south-southeast across remnant oily soils in landfarm area



- Photo 9 – Concrete debris in landfarm area



- Photo 10 – Concrete and metal debris, remnant oily soil in landfarm area



- Photo 11 – Pipe section located north of landfarm area, removed during inspection.