

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/04/2020

Submitted Date:

12/11/2020

Document Number:

699700222

FIELD INSPECTION FORM
 Loc ID 335928 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Middleton, Brett		bmiddleton@caerusoilandgas.com	Sr. Environmental Specialist
Arauz, Steven		steven.arauza@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293666	WELL	SI	01/01/2020	GW	045-15092	DWU CP08B-33 E34 49	EI
293668	WELL	PR	10/07/2014	GW	045-15094	DWU CP01B-33 E34 49	EI
431593	WELL	PR	09/11/2014	GW	045-21859	SG 8506A-34 E34496	EI
431729	WELL	PR	01/01/2020	SI	045-21866	SG 8511D-34 E34496	EI
431942	WELL	PR	09/01/2019	SI	045-21899	SG 8514D-34 E34496	EI
431943	WELL	DG	09/11/2013	SI	045-21900	SG 8508F-33 E34496	EI
431944	WELL	PR	08/01/2019	SI	045-21901	SG 8509E-33 E34496	EI
431945	WELL	PR	12/01/2019	SI	045-21902	SG 8509A-33 E34496	EI
431946	WELL	PR	09/11/2014	GW	045-21903	SG 8503D-34 E34496	EI
431947	WELL	PR	11/01/2019	SI	045-21904	SG 8509D-33 E34496	EI
431948	WELL	PR	08/01/2019	SI	045-21905	SG 8516A-33 E34496	EI
431949	WELL	PR	08/01/2019	SI	045-21906	SG 8515E-34 E34496	EI
431950	WELL	PR	08/01/2019	SI	045-21907	SG 8516B-33 E34496	EI
431951	WELL	PR	07/17/2014	GW	045-21908	SG 8506C-34 E34496	EI
431954	WELL	PR	12/01/2019	SI	045-21909	SG 8506D-34 E34496	EI
431955	WELL	SI	04/01/2020	GW	045-21910	SG 8503E-34 E34 496	EI
431956	WELL	SI	04/01/2020	GW	045-21911	SG 8508D-33 E34496	EI
431957	WELL	PR	09/01/2019	SI	045-21912	SG 8514C-34 E34496	EI

431958	WELL	PR	01/01/2020	SI	045-21913	SG 8515D-34 E34496	EI
431959	WELL	PR	06/01/2014	GW	045-21914	SG 8503C-34 E34496	EI
431960	WELL	PR	12/01/2019	SI	045-21915	SG 8515F-34 E34496	EI
431961	WELL	PR	08/01/2019	SI	045-21916	SG 8514E-34 E34496	EI
431962	WELL	PR	11/01/2019	SI	045-21917	SG 8509C-33 E34496	EI
431963	WELL	PA	01/27/2019	DA	045-21918	SG 8511E-34 E34496	EI
431964	WELL	PR	12/01/2019	SI	045-21919	SG 8514A-34 E34496	EI
431965	WELL	DG	11/17/2018	SI	045-21920	SG 8508E-33 E34496	EI
431966	WELL	PR	09/01/2019	SI	045-21921	SG 8516C-33 E34496	EI
431967	WELL	PR	09/01/2019	SI	045-21922	SG 8516E-33 E34496	EI
431968	WELL	PR	04/25/2020	SI	045-21923	SG 8511A-34 E34496	EI
431969	WELL	PR	11/01/2019	SI	045-21924	SG 8509B-33 E34496	EI
431970	WELL	PR	06/13/2014	GW	045-21925	SG 8506B-34 E34496	EI
431971	WELL	PR	01/01/2020	SI	045-21926	SG 8506E-34 E34496	EI
431974	WELL	SI	04/01/2020	GW	045-21927	SG 8503B-34 E34496	EI
431976	WELL	PR	08/01/2019	SI	045-21928	SG 8511C-34 E34496	EI
475142	SPIILL OR RELEASE	CL	08/10/2020		-	E34 frac pad	EI

General Comment:

On November 4, 2020, COGCC Staff (John Heil and Aaron Trujillo) conducted a field inspection of CAERUS PICEANCE LLC (Caerus operator #10456) SG E34 496 Location ID 335928.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at wells (API # 05-045-21900 & API # 05-045-21918)		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	01/11/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	unmarked riser		
Corrective Action:	For unused , unmarked flow line risers 24 hrs. to lock out tag out. 30 days to remove riser.	Date:	12/14/2020
Type	TRASH		
Comment:	Site wide trash and debris (see photos)		
Corrective Action:	Comply with Rule 603.f.	Date:	12/26/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on the north side of the locaiton.		
Corrective Action:	Comply with Rule 603.f .	Date:	12/26/2020

Overall Good: ☐

Spills:				
Type	Area	Volume		
Other		<= 1 bbl		
Comment:	Site wide accumulations of oily waste.			
Corrective Action:	Properly dispose of oily waste in accordance with 907.e.			Date: 12/25/2020

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>293666</u>	Type: <u>WELL</u>	API Number: <u>045-15092</u>	Status: <u>SI</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293668</u>	Type: <u>WELL</u>	API Number: <u>045-15094</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431593</u>	Type: <u>WELL</u>	API Number: <u>045-21859</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431729</u>	Type: <u>WELL</u>	API Number: <u>045-21866</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431942</u>	Type: <u>WELL</u>	API Number: <u>045-21899</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431943</u>	Type: <u>WELL</u>	API Number: <u>045-21900</u>	Status: <u>DG</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431944</u>	Type: <u>WELL</u>	API Number: <u>045-21901</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431945</u>	Type: <u>WELL</u>	API Number: <u>045-21902</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431946</u>	Type: <u>WELL</u>	API Number: <u>045-21903</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431947</u>	Type: <u>WELL</u>	API Number: <u>045-21904</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431948</u>	Type: <u>WELL</u>	API Number: <u>045-21905</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431949</u>	Type: <u>WELL</u>	API Number: <u>045-21906</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431950</u>	Type: <u>WELL</u>	API Number: <u>045-21907</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431951</u>	Type: <u>WELL</u>	API Number: <u>045-21908</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431954</u>	Type: <u>WELL</u>	API Number: <u>045-21909</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431955</u>	Type: <u>WELL</u>	API Number: <u>045-21910</u>	Status: <u>SI</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431956</u>	Type: <u>WELL</u>	API Number: <u>045-21911</u>	Status: <u>SI</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431957</u>	Type: <u>WELL</u>	API Number: <u>045-21912</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431958</u>	Type: <u>WELL</u>	API Number: <u>045-21913</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>

Facility ID:	431959	Type:	WELL	API Number:	045-21914	Status:	PR	Insp. Status:	EI
Facility ID:	431960	Type:	WELL	API Number:	045-21915	Status:	PR	Insp. Status:	EI
Facility ID:	431961	Type:	WELL	API Number:	045-21916	Status:	PR	Insp. Status:	EI
Facility ID:	431962	Type:	WELL	API Number:	045-21917	Status:	PR	Insp. Status:	EI
Facility ID:	431963	Type:	WELL	API Number:	045-21918	Status:	PA	Insp. Status:	EI
Facility ID:	431964	Type:	WELL	API Number:	045-21919	Status:	PR	Insp. Status:	EI
Facility ID:	431965	Type:	WELL	API Number:	045-21920	Status:	DG	Insp. Status:	EI
Facility ID:	431966	Type:	WELL	API Number:	045-21921	Status:	PR	Insp. Status:	EI
Facility ID:	431967	Type:	WELL	API Number:	045-21922	Status:	PR	Insp. Status:	EI
Facility ID:	431968	Type:	WELL	API Number:	045-21923	Status:	PR	Insp. Status:	EI
Facility ID:	431969	Type:	WELL	API Number:	045-21924	Status:	PR	Insp. Status:	EI
Facility ID:	431970	Type:	WELL	API Number:	045-21925	Status:	PR	Insp. Status:	EI
Facility ID:	431971	Type:	WELL	API Number:	045-21926	Status:	PR	Insp. Status:	EI
Facility ID:	431974	Type:	WELL	API Number:	045-21927	Status:	SI	Insp. Status:	EI
Facility ID:	431976	Type:	WELL	API Number:	045-21928	Status:	PR	Insp. Status:	EI
Facility ID:	475142	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: An active landfarm was observed on the west side of the location. Multiple pieces of trash and debris were observed within the landfarm material at time of inspection.

Corrective Action: All foreign materials other than cuttings shall be removed from cuttings disposal area. Land Treatment of oily waste shall be performed in strict accordance with the requirements of COGCC Rule 907.e.(2). Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700232	20201104 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308787