



• Photo 1 –



- Photo 2 –



- Photo 3 – Chemical drum outside secondary containment



- Photo 4 – Excavation around meter shed



- Photo 5 – Excavation around separator



- Photo 6 – Excavation around separator



- Photo 7 – Impacted soil stockpiled on plastic



- Photo 8 – Impacted soil stockpiled on plastic



- Photo 9 – Separator excavation



- Photo 10 – Meter shed excavation



- Photo 11 – Oily soil at State #5 wellhead



- Photo 12 – Oily soil at State #5 wellhead