



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Well after casing cut off below ground level with hood on.

Runknow 35-11

API: 05-103-12422

Inspection: 700404549











40.09911, -108.85564, 5142.0ft, 313°
12/10/2020 01:48:59 PM




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Location after well plugged and back filled with dirt.

Runknown 35-11

API: 05-103-12422

Inspection: 700404549



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. FLIR image with HSM before 3' plug added.

Runkown 35-11

API: 05-103-12422

Inspection: 700404549